


**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. 5031Date : 8-10-2018

It is certified that an inspection team headed by SH. VASUDEN GARG, S.O. (P.H.I.) & SH. GURINDER SINGH J.E. PH-I (Name of Officers with designation) from DIVISIONAL ENGINEER (P.H.I.) (Name of Department/Office) inspected the KENDRIYA VIDYALAYA MOHALI SECTOR 80, MOHALI-PUNJAB-140308 (Name & Address of the School) on 8-10-2018 and found that KENDRIYA VIDYALAYA MOHALI SECTOR 80 (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of 3 (three) years.

Signature with Seal : 

Name

: Ex. VASUDEN

Designation

DivisionalEngineerGurgaon

Divisional Engineer,
Public Health Division No.1
GMADA, S.A.S. Nagar

To

KENDRIYA VIDYALAYA MOHALI
SECTOR 80
NEAR MAULI BAIDWAN
SAS NAGAR MOHALI-PUNJAB 140308

(Name & Address of the Institution)

2

It is certified that
safe drinking water
being supplied to the
institution through Govt
Supply Unit
Sector 80
S.O. (P.H.I.)